



## Vehicle Running Report for the date 2020-12-09

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	801476		354017117821393	08:05:30	19:13:59	04:22:19
2	215942		359632103754146	08:04:09	17:38:30	04:18:13
3	217633		354017117835831	07:10:44	22:53:34	04:18:19
4	562208		354017117810768	06:35:20	14:34:12	00:14:57
5	790965		354017117442406	08:01:02	20:06:44	02:53:17
6	190621		354017117442315	07:23:27	17:18:32	03:15:15
7	172573		354017117442273	06:23:24	21:35:15	04:24:13
8	537866		354017117442364	06:47:24	17:31:58	03:01:38
9	183378		354017117834651	06:30:42	17:19:13	04:43:57
10	743752		354017117442182	07:39:40	17:55:19	03:05:18
11	167973		354017117815171	07:34:15	18:15:43	02:11:17
12	178363		359633100068779	08:12:29	16:37:35	00:06:54
13	783266		359633100055982	07:39:52	20:39:07	03:57:23
14	790972		359633100061287	04:02:13	21:22:07	09:27:35
15	801475		359633100061337	08:39:20	15:18:50	01:29:51
16	217981		354017117819488	07:09:26	21:34:06	02:40:16
17	435687		354017117833794	06:17:05	23:53:59	03:30:20
18	790973		359633100065726	10:34:43	17:14:58	01:03:59
19	793012		354017117442125	16:10:14	16:11:15	00:00:06
20	790978		359633100052567	07:42:44	17:42:29	02:18:15
21	792996		354017117836854	09:24:37	21:47:05	06:02:59
22	267530		359632109060860	01:19:19	09:45:49	01:48:47

## Vehicle Running Report for the date 2020-12-09

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engin ON Time
23	799035		359632109060803	05:34:02	20:50:31	01:12:59
24	782933		354017117817292	07:55:26	23:15:35	01:57:27
25	197098		354017117819439	08:42:48	20:14:29	00:57:44
26	458389		354017117836870	01:04:34	23:59:54	04:03:29
27	537518		354017117442208	08:24:29	18:03:42	04:37:08
28	180751		359633100056113	09:16:07	22:35:02	03:39:35
29	267107		354017117819629	07:56:28	17:15:32	02:52:38
30	556903		354017117817425	08:05:38	17:08:02	00:46:33
31	793011		359633100056014	08:23:34	15:21:56	00:51:54
32	790975		354017117833810	02:07:38	10:07:57	01:49:33
33	798970		359633100064935	00:00:01	23:50:41	07:09:18
34	745893		359633100065742	07:14:20	17:30:05	02:45:19
35	813692		354017117833687	06:32:12	19:26:52	01:56:16
36	786836		359633100052328	08:37:22	16:38:35	03:39:13
37	169421		359632109058294	07:26:53	20:21:42	00:49:35
38	682817		354017117442166	06:18:55	17:02:20	01:55:03
39	170392		354017117442232	06:01:05	19:47:34	08:53:43
40	568501		354017117808150	07:25:42	18:57:32	01:38:01
41	190855		354017117810842	12:41:57	22:18:17	02:46:22
42	189507		354017117834453	07:58:03	19:22:46	02:37:03
43	799034		359632109058310	06:54:16	17:55:21	01:46:49
44	266150		354017117819496	07:59:31	22:42:32	04:35:24
45	572851		354017117804449	07:55:07	22:21:25	07:21:03
46	171364		354017117442240	07:38:00	17:24:30	06:16:56
47	816971		354017117810834	07:41:17	18:15:45	00:37:28
48	816970		359633100064554	07:55:02	17:31:46	00:56:42

**Vehicle Running Report for the date 2020-12-09**

<b>SL NO</b>	<b>Vehicle Number/Name</b>	<b>Driver Name</b>	<b>Vehicle IMEI</b>	<b>First Ignition</b>	<b>Last Ignition</b>	<b>Total Engine ON Time</b>
49	781927		354017117821187	06:05:05	23:20:00	10:30:54
50	793013		359633100057921	19:58:16	22:01:29	00:29:18
51	790976		359633100036206	07:29:44	22:27:13	03:06:20