



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-21

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	00:01:32	15:24:40	03:21:14
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:01:50	19:06:34	05:23:32
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:05:25	18:25:08	05:13:53