



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-18

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	10:32:34	17:16:12	00:00:35
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	05:53:01	22:37:14	01:18:51
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	07:51:13	17:06:12	00:08:37