



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-05

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:59:33	17:34:09	03:14:32
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	01:19:19	23:42:37	07:58:58
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:07:29	19:03:19	04:34:46