



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-23

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	03:46:17	17:07:42	03:25:17
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	06:16:52	21:13:42	03:59:58
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:11:18	17:56:21	05:53:53