



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-22

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:39:41	23:02:23	01:41:08
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:38:32	23:16:03	01:58:18
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:08:42	12:07:49	02:55:38