



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-09

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	00:54:32	15:57:19	04:59:45
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	04:23:46	20:02:35	05:42:47
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	05:58:31	19:09:51	07:14:48