



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-14

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:21:56	23:32:34	00:10:08
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	06:24:01	23:48:58	01:30:38