



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-20

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:38:57	15:39:09	03:31:49
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	01:51:11	23:55:34	07:39:26
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:08:19	17:45:03	05:44:33