



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-28

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	04:50:37	21:12:14	03:56:18
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:19:45	22:37:39	04:39:55
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:10:49	19:50:18	04:54:32