



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-10-09

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	10:53:11	17:44:12	00:03:31
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	04:51:59	23:56:11	00:01:48
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	16:13:40	16:45:01	00:10:53