



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-10

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	13:43:20	14:38:25	00:00:00
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	10:07:10	19:05:15	00:00:52