



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-12

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	01:12:35	22:20:43	05:25:55
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:39:11	21:34:54	04:33:28
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:03:42	18:44:29	07:34:12