



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-17

| SL NO | Vehicle Number/Name | Driver Name | Vehicle IMEI | First Ignition | Last Ignition | Total Engine ON Time |
|-------|----------------------------|-------------|-----------------|----------------|---------------|----------------------|
| 1 | AD-1-87470-MITSUBISHI ROSA | | 867604055799531 | 07:04:34 | 18:49:43 | 04:33:35 |
| 2 | AD-2-85577-MITSUBISHI ROSA | | 867604055806815 | 00:00:40 | 23:31:28 | 03:51:33 |
| 3 | AD-1-73769-MITSUBISHI ROSA | | 867604055817515 | 06:03:29 | 18:16:21 | 04:03:07 |