



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-30

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	13:38:19	19:29:43	00:01:30
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:19:20	23:49:26	02:05:34